NACRE SOOTHING SHADES

Application

Prepare your walls with the **Primer before paint**.

Pearly effect: Apply a thin coat of **Nacre** with a roller. Leave to dry ±4h.

Apply directly a second coat of Nacre with the Spatola or Stainless steel float, in a wavelike motion in all directions to bring out the shimmers of pearl.

On panelling:

Apply Nacre with a To get a beaded pearl **Spalter** in the grain direction. Well smooth to avoid over-thicknesses. Allow to dry ±2h.

necessary on your surface previously lightly sanded.

Beaded pearl effect:

effect, add a can of Silk beads in the can of Nacre. Mix well and apply 2 thin coats using a Spalter Apply a second coat if in irregular crisscross movements. Allow to dry ±4 hours between coats.



LET'S PAINT!

*Adding beads into paint will not change its coverage.

PEARLY VELVET PAINT

IDEAL IN BATHROOMS WASHABLE - HIGHLY RESISTANT HIGH COVERAGE: 2L = 12m² **WALL-WOODWORK**

NACRE, products and associated tools















CLEANING WITH WATER

Join the Creative Revolution! id-paris.com - (\bigcirc (\mathbf{f}) (You Tube)





INITIATIVES DÉCORATION BP30027 - 17301 Rochefort France +33 5 46 88 88 00 - id-paris.com













#CREATIVE REVOLUTION

Assert your style

NACRE



Cassis

